

# Polyurethane/Nitril Rubber

Highly recommended 

Recommended 

Variable (contact us) 

Not recommended 

	CLASSIC & DELUXE	COMPLETE BUBBLE, SMOOTH & DELUXE	COMPLETE BUBBLE & SMOOTH ESD	INFINITY BUBBLE, BUBBLE ESD, SMOOTH ESD, DELUXE & DELUXE ESD	BUBBLE DOWN	BASIC BUBBLE, SMOOTH & BUBBLE DOWN	SOFTLINE	NITRO	NITRIL & NITRIL SMOOTH	NITRIL ESD-CONDUCTIVE & SMOOTH ESD	INDUSTRY	HYGIENE	SUPER SAFE SMOOTH & ERGO ANTI-MICROBIAL	INDUSTRY BASIC
Dry usage area														
Wet usage area														
Static control														
Fire retardant														
Slip prevention														
Welding area/Embers														
Customized mats/Drawings														
Outdoor														
Mineral oils														
Vegetable oils														
Cooling/cutting fluids														
Cutting oils/fluids include esters and amines														
Alkaline liquids pH: 7-9.5														
Alkaline liquids pH: 9.5-14														
Acids pH: 2-7														
Acids pH: 0-2														
Disinfectants														
Chloride solutions in water														
Solvents (aromatic/aliphatic)														
Phthalates (and related softeners)/Ketones/Aldehyde/Esters/Amines)														
Alcohol														

## User Instructions Polyurethane/Rubber

	Classic/Complete Bubble/Complete Smooth/Basic Bubble/Basic Smooth /EBF/EFS/ Bubble Down/	Deluxe/Infinity Bubble/Infinity Smooth	Softline/Nitro/Nitril/Nitril ESD/Nitril CON/Nitril F/Industry/Industry basic	Hygiene/Safe Mat/Super Safe-Mat/ Ergo Anti-Microbial
Suitable for usage	Dry areas	Dry areas	Dry and wet areas	Dry and wet areas
Temperature	40° to 95° F 5° to 35° C	40° to 95° F 5° to 35° C	-40° to 195° F -40° to 90° C	-40° to 250° F -40° to 120° C
Cleaning	<ul style="list-style-type: none"> <li>Sweeping</li> <li>Vacuuming</li> <li>Washing in mild soap (pH: 6-8) with subsequently careful wiping so all water is removed</li> </ul>	<ul style="list-style-type: none"> <li>Sweeping</li> <li>Vacuuming</li> <li>Washing in mild soap (pH: 2-9.5).</li> <li>If the backside of the mat gets wet during the washing, the mat must lie upside down until it is dry and all the moisture has evaporated.</li> </ul>	<ul style="list-style-type: none"> <li>Sweeping</li> <li>Vacuuming</li> <li>Wet mopping with mild soap (pH 5-9)</li> <li>Pressure washing 1,000 -1,500 PSI (70 - 100 BAR) at a minimum distance of 8"</li> <li>Autoclavable in 2'x3' (60 x 90 cm) size only. Dry the mat horizontally and flat. Avoid bending.</li> </ul>	<ul style="list-style-type: none"> <li>Sweeping</li> <li>Vacuuming</li> <li>Wet mopping water based cleaning agent (pH 1-13)</li> <li>Pressure washing 1,000 - 1,500 PSI (70 - 100 BAR) at a minimum distance of 8"</li> <li>Autoclavable in 2'x3' (60 x 90 cm) size only</li> <li>Dry the mat horizontally and flat. Avoid bending.</li> </ul>

Cleaning the mats is the responsibility of the end-user. Warranty will be voided on mats that are not appropriately maintained. If you have any additional questions, please contact your **ERGOMAT**® distributor